

Tri Special Utility District
300 West 16th Street
Mount Pleasant TX 75455

The following notice has been attached to our outgoing statements. This is a reporting violation only.

The TRI SUD water system PWS ID 2250004 has violated the reporting requirements set by Texas Commission on Environmental Quality (TCEQ) in Title 30, Texas Administrative Code (30 TAC), Sec 290, Subchapter F. Public water systems are required to properly disinfect water before distribution, maintain acceptable disinfection residuals within the distribution system, monitor the disinfectant residual at various locations throughout the distribution system, and report the results of that monitoring to the TCEQ on a quarterly basis.

Results of regular monitoring are an indicator of whether or not your drinking water is safe from microbial contamination.

This reporting violation occurred in the monitoring period of January 2017. **Our report was not received by the due date. All disinfectant levels were within acceptable range, and there is no further corrective action to be taken.**

We are required to share this information with all people who drink this water, especially those who may not have received this notice directly (i.e., people in apartments, nursing homes, schools, and businesses). You can share this by posting this notice in a public place or by distributing copies.

If you have questions regarding this matter, you may contact Becki Brantley at 903-572-3676 x13.

Notice delivered 3/31/17